Burnside Road @ Seaton Street

Tuesday, March 13, 2018



The data presented here is for information purposes only and should not be considered authoritative for construction, geotechnical, engineering, navigational, legal, or other site-specific uses. The information shared is owned by the Transportation Division of the Engineering Department at the District of Saanich. Accuracy is not guaranteed.

Major Route: Burnside Road


Minor Route: Seaton Street


Tuesday, March 13, 2018 Date:

Filename: Burnside@Seaton-Mar13-2018.xls Station #: TIN001018

Intersection Type: 3-leg north approach East/West Route: **Burnside Road**

Weather: Cloudy and dry





Major Route: Burnside Road Station #: TIN001018


Minor Route: Seaton Street Intersection Type: 3-leg north approach

Date:Tuesday, March 13, 2018East/West Route:Burnside RoadFilename:Burnside@Seaton-Mar13-2018.xlsWeather:Cloudy and dry

Comments:

Vehicle Data

Time	S	eaton S	St				Bu	rnside	Rd	Bu	Burnside Rd							
Period	Fr	om No	rth	Fre	om Sou	ıth	Fr	om West		From East		15 Min	Hourly	ı	Pedes	trians	3	
Starting	Left	Thru	Right	Left	Thru	Right	Left	Thru	Right	Left	Thru	Right	Total	Total	N	S	W	Е
7:30	1		1				2	276			80	2	362	-	0		6	0
7:45	1		1				0	312			120	2	436	-	7		11	0
8:00	2		3				1	283			137	0	426 *	-	5		8	0
8:15	2		8				2	283			136	7	438 *	1662	3		4	0
8:30	2		8				3	294			146	5	458 +	1758	12		37	0
8:45	2		5				7	311			131	2	458 *	1780	3		20	0
9:00	1		6				3	233			124	3	370	1724	0		3	0
9:15	2		0				0	194			132	3	331	1617	4		6	0
Total	13	0	32	0	0	0	18	2186	0	0	1006	24	3279	-	34	0	95	0
Pk Hr	8	0	24	0	0	0	13	1171	0	0	550	14	1780 *	-	23	0	69	0
Pk Hr	1.00	n/a	0.75	n/a	n/a	n/a	0.46	0.94	n/a	n/a	0.94	0.50	0.97	* = Pea	k hou	ır		
				, 0.	.,, 0.	, 0.	0	0.0.	, 0.	. ι, α	0.0 .	0.00	0.07					
Factor		0.80		, «	n/a	, 🗸	0.10	0.93	, &	1,,α	0.93	0.00	0.01	+ = Pe			es	
Factor 15:30	0	0.80	6	, .		, .	3	0.0	.,, &	11/0		6	486 *	1			es 0	0
	0	0.80		.,,		.,,		0.93	.,,	1170	0.93			1	ak 15			0
15:30		0.80	6				3	0.93	.,,	11,0	0.93 291	6	486 *	1	ak 15 2		0	
15:30 15:45	0	0.80	6 3				3	0.93 180 171		17/4	0.93 291 283	6	486 * 464 *	1	ak 15 2		0	0
15:30 15:45 16:00	0 2	0.80	6 3 7				3 1 4	0.93 180 171 179		.,,	0.93 291 283 323	6 6 1	486 * 464 * 516 +	+ = Pea	ak 15 2 4 1		0 9 7	0
15:30 15:45 16:00 16:15	0 2 0	0.80	6 3 7 5				3 1 4 3	0.93 180 171 179 162			0.93 291 283 323 319	6 6 1 7	486 * 464 * 516 + 496 *	+ = Pea - - - 1962	2 4 1 2		0 9 7 7	0 0
15:30 15:45 16:00 16:15 16:30	0 2 0 2	0.80	6 3 7 5 6				3 1 4 3 2	0.93 180 171 179 162 176			291 283 323 319 290	6 6 1 7 4	486 * 464 * 516 + 496 * 480	+ = Pea - - - 1962 1956	2 4 1 2		0 9 7 7 8	0 0 0
15:30 15:45 16:00 16:15 16:30 16:45	0 2 0 2 2	0.80	6 3 7 5 6				3 1 4 3 2 3	0.93 180 171 179 162 176 160		1,70	291 283 323 319 290 230	6 6 1 7 4 3	486 * 464 * 516 + 496 * 480 399	+ = Pea - - - 1962 1956 1891	2 4 1 2 2		0 9 7 7 8 9	0 0 0 0
15:30 15:45 16:00 16:15 16:30 16:45 17:00	0 2 0 2 2 2	0.80	6 3 7 5 6 1	0		0	3 1 4 3 2 3 7	0.93 180 171 179 162 176 160 204	0	0	0.93 291 283 319 290 230 215 282 2233	6 6 1 7 4 3	486 * 464 * 516 + 496 * 480 399 434	+ = Period	2 4 1 2 2 1 2		0 9 7 7 8 9 5 2	0 0 0 0 0
15:30 15:45 16:00 16:15 16:30 16:45 17:00 17:15 Total Pk Hr	0 2 0 2 2 2 2 2 2		6 3 7 5 6 1 5 9		n/a		3 1 4 3 2 3 7 5 28	0.93 180 171 179 162 176 160 204 166			0.93 291 283 323 319 290 230 215 282	6 6 1 7 4 3 1 1 29 20	486 * 464 * 516 + 496 * 480 399 434 465	+ = Pea - - - 1962 1956 1891 1809 1778	2 4 1 2 2 2 1 2	minut	0 9 7 7 8 9 5 2	0 0 0 0 0 0
15:30 15:45 16:00 16:15 16:30 16:45 17:00 17:15	0 2 0 2 2 2 2 2	0	6 3 7 5 6 1 5 9	0	n/a	0	3 1 4 3 2 3 7 5	0.93 180 171 179 162 176 160 204 166 1398	0	0	0.93 291 283 323 319 290 230 215 282 2233 1216	6 6 1 7 4 3 1 1	486 * 464 * 516 + 496 * 480 399 434 465	+ = Pea - - - 1962 1956 1891 1809 1778	2 4 1 2 2 1 2 1 5	minut	0 9 7 7 8 9 5 2	0 0 0 0 0 0 0



Major Route: Burnside Road


Minor Route: Seaton Street


Date: Tuesday, March 13, 2018

Filename: Burnside@Seaton-Mar13-2018.xls Station #: TIN001018

Intersection Type: 3-leg north approach East/West Route: **Burnside Road**

Weather: Cloudy and dry





Major Route: Burnside Road Station #: TIN001018

Minor Route: Seaton Street

Date: Tuesday, March 13, 2018

Filename: Burnside@Seaton-Mar13-2018.xls

Station #: TIN001018
Intersection Type: 3-leg north approach

East/West Route: Burnside Road
Weather: Cloudy and dry

Comments:

Bicycle Data

Time	Seaton St						Bu	rnside	Rd	Bu	rnside	Rd		
Period	From North		From South			From West			From East			15 Min	Hourly	
Starting	Left	Thru	Right	Left	Thru	Right	Left	Thru	Right	Left	Thru	Right	Total	Total
7:30	0		1				1	3			3	0	8 +	-
7:45	0		0				0	0			1	0	1 *	-
8:00	0		0				0	0			2	0	2 *	-
8:15	0		0				0	2			1	0	3 *	14
8:30	0		0				0	1			0	0	1	7
8:45	1		0				0	0			0	0	1	7
9:00	0		0				0	0			0	0	0	5
9:15	0		0				0	0			0	0	0	2
Total	1	0	1	0	0	0	1	6	0	0	7	0	16	-
Pk Hr	0	0	1	0	0	0	1	5	0	0	7	0	14 *	-
15x4	0	0	4	0	0	0	4	12	0	0	12	0	32 +	-

15:30	0		2				0	1			1	0	4 +	-
15:45	0		0				0	0			3	0	3 *	-
16:00	1		1				0	2			0	0	4 *	-
16:15	0		1				0	0			0	1	2 *	13
16:30	0		0				1	0			0	0	1	10
16:45	0		0				0	0			0	0	0	7
17:00	0		0				0	0			0	0	0	3
17:15	0		0				0	0			0	0	0	1
Total	1	0	4	0	0	0	1	3	0	0	4	1	14	-
Pk Hr	1	0	4	0	0	0	0	3	0	0	4	1	13 *	-
15x4	4	0	8	0	0	0	0	8	0	0	12	4	16 +	-

4 Hr 2 0 5 0 0 0 2 9 0 0 11 1 30	60
----------------------------------	----

